## **NOTES:**

- 1) Fly Ash Samples- need to be taken during each test period (need support of 2 Operators for fly ash sample collection). Fly Ash Hoppers need to be pulled down <u>prior to the test (night shift)</u> and <u>between each test point</u>. ISG will be collecting the fly ash samples at each test points. All fly ash hopper rows need to be available (no maintenance work)
- 2) Coal Samples will also be taken at each test point at the coal feeder inlet (new test coal sample collection ports). Note: there may be a certain amount of coal spillage created while collecting these coal samples.
- 3) Bottom ash samples will also be collected during some of the tests.
- 4) Do not washdown boiler in the backpass areas, due to test equipment, analyzers and computers.
- 5) PI system needs to be up and running, no downtime or backups
- 6) CEM system PI interface needs to be working